| ECS Configuration Change Request   |  |  |                   |            | Page 1 of Page             |                            | je(s)                                 |             |  |
|--|--|--|-------------------|------------|----------------------------|----------------------------|---------------------------------------|-------------|--|
| 1. Originator  | 2. Log Date:   | 3. CCR #:  |                   | 4. Rev:    | 5. Tel:                    | •                          | 6. Rm #:                              | 7. Dept.    |  |
| Mike Molinet   | 9/9/02   | 02-0767  |                   | _          | 301.925.0874               | 2                          | 2038A                                 | SE_TS       |  |
| 8. CCR Title: Update PVC NFS Mount Points for SSIT in String 2 - OPS, TS1, and TS2 modes ONLY  |  |  |                   |            |                            |                            |                                       |             |  |
| 9. Originator Signature/Date   |  |  | 10. Class         |            | 11. Type: 12               |                            | 2. Need Date: 9/12/02                 |             |  |
| Mike Molinet /s/ 9/9/02  |  |  | IN                | -          | CCR                        |                            |                                       |             |  |
| 13. Office Manager Signature/Date  |  |  | 14. Category of   |            |                            |                            | <b>15. Priority: (</b> If "Emergency" |             |  |
| Arthur Cohen /s/ 7/9/02  |  |  |                   | eline Doc. | fill in Block 27). Routine |                            |                                       |             |  |
| 16. Documentation/Drawings Impacted: 920-TDP-008:REV 15  |  |  |                   | dule       | 18. CI(s) A                | CI(s) Affected:PDPS, STMGT |                                       |             |  |
| 19. Release Affected by this Change: 20. Date due  |  |  | to Custo          |            |                            |                            |                                       |             |  |
| 6A   |  |  | None - Under 100K |            |                            |                            |                                       |             |  |
| 22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☐Other:  |  |  |                   |            |                            |                            |                                       |             |  |
| 23. Problem: (use additional Sheets if necessary)  |  |  |                   |            |                            |                            |                                       |             |  |
| Additional NFS Mount Points needed for SSIT in String 2 in PVC.  |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
| 24. Proposed Solution: (use additional sheets if necessary)  |  |  |                   |            |                            |                            |                                       |             |  |
| Add the mount points listed as "rev. 15" on the attached spreadsheet. OPS, TS1, and TS2 modes ONLY.  |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
| 25. Alternate Solution: (use additional sheets if necessary)   |  |  |                   |            |                            |                            |                                       |             |  |
| N/A  |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
| 26. Consequences if Change(s) are not approved: (use additional sheets if necessary)   |  |  |                   |            |                            |                            |                                       |             |  |
| SSIT configuration will continue to be incorrect for SSIT in the PVC String 2.   |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
| 27. Justification for Emergency (If Block 15 is "Emergency"):  |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
| 28. Site(s) Affected: Dede Dede Dede Description Descr |  |  |                   |            |                            |                            |                                       |             |  |
| ☐EOC ☐ IDG Test Cell ☐Other  |  |  |                   |            |                            |                            |                                       |             |  |
| 29. Board Comments:  |  |  |                   | 30. V      | Work Assigned T            | o: 3                       | 31. CCR C                             | losed Date: |  |
|  |  |  |                   |            |                            |                            |                                       |             |  |
| 32. EDF/SCDV CCB Chair (Sign/Date): Disposition: Ap  |  |  |                   | Ann/C      | om. Disapproved            | -  <br>-                   | thdraw Fw                             | rd/ESDIS    |  |
| Otai Harley /s/ 9/11/02  | ER   | -  | -p.0104           | , .pp, 0   | Jioappiove                 | VVIL                       |                                       | J., 20010   |  |
| Byron V. Peters /s/ 9/1/<br>33. M&O CCB Chair (Sign/I  |  | isposition: Ar   | pproved           | App/Co     | om. Disapproved            | \/\/i+l                    | hdraw Fwo                             | /FSDIS FRR  |  |
| out inde oob ondir (orgive   | 20.0).   | <b>Disposition:</b> Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS |                   |            |                            |                            |                                       |             |  |
| 24 ECC CCD Ch -!- /0!- /D  | loto).   |  |                   | Ann /O :   | m Diagram                  | 1 ///:                     | halrow F                              | 4/F0D10 FD5 |  |
| 34. EUS CUB Chair (Sign/D  | 44. ECS CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERI |  |                   |            |                            |                            |                                       |             |  |
| Fwd/ESDIS  |  |  |                   |            |                            |                            |                                       |             |  |